

CHAMPION AIRCRAFT CORPORATION
Osceola, Wisconsin

SERVICE LETTER #70
FAA Approved

DATE: February 8, 1967
SUBJECT: Rudder Cable Pulley Lubrication
MODELS AFFECTED: All Model 7 Aircraft
TIME OF COMPLIANCE: During 100-Hour or Annual Inspection or
as Required

To prevent binding of aluminum rudder cable pulleys (located just aft of or in baggage compartment) and subsequent excessive wear of pulleys and/or cables, inspect pulleys periodically for freedom of operation and lubricate as necessary with MIL-L-3545 or equivalent grease, SAE 20 oil mixed with graphite, or SAE 20 oil.