

50-TL

SA02033AT (PAGE 1)	Modification to install an air-oil separator to prevent oil from being aspirated from the engine	Amended	07/25/2008
SA1109GL	Surrendered and incorporated into STC SA00478CH.	Surrendered	06/14/2002
SA1350WE	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with fiberglass cloth.	Reissued	03/06/1969
SA308EA(1 OF 2)	Installation of carburetor ice detection system 105AP in single and twin engine aircraft and single	Amended	11/20/1978
SA4-1210	Installation of Eonnex cover on aircraft surfaces.	Reissued	08/19/1980
SA4-302	Installation of BN-1 propeller spinner.	Reissued	10/30/1985
SA4624NM	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
SA489EA	Installation of ARP Inc. carburetor ice detection system	Amended	12/05/2002
SA5159NM(1 OF 2)	Installation of chip detector system.	Amended	11/06/1992
SA798EA	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972