

**65-TL**

<a href="#">SA02033AT (PAGE 1)</a>	Modification to install an air-oil separator to prevent oil from being aspirated from the engine	Amended	07/25/2008
<a href="#">SA1109GL</a>	Surrendered and incorporated into STC SA00478CH.	Surrendered	06/14/2002
<a href="#">SA1350WE</a>	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with fiberglass cloth.	Reissued	03/06/1969
<a href="#">SA308EA(1 OF 2)</a>	Installation of carburetor ice detection system 105AP in single and twin engine aircraft and single	Amended	11/20/1978
<a href="#">SA4-1210</a>	Installation of Eonnex cover on aircraft surfaces.	Reissued	08/19/1980
<a href="#">SA4-302</a>	Installation of BN-1 propeller spinner.	Reissued	10/30/1985
<a href="#">SA4624NM</a>	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
<a href="#">SA489EA</a>	Installation of ARP Inc. carburetor ice detection system	Amended	12/05/2002
<a href="#">SA5159NM(1 OF 2)</a>	Installation of chip detector system.	Amended	11/06/1992
<a href="#">SA798EA</a>	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972