

CHAMPION AIRCRAFT CORPORATION  
Osceola, Wisconsin

Reissued February 21, 1961  
Reissued February 19, 1969

SERVICE LETTER #11

SUBJECT: Factory Installation of 1-2565 Bronze Oleo Bushings in 4-541 & 4-10001 Oleo Case Frames.

We have established the following plan to provide service on Oleo Case Frame Rebushing. In some cases you will be furnished with a new Cases Frame in the event we don't have sufficient rebushed frames on hand.

- 1) All Oleo Case Frames must come in Uncovered and Without the Oleo.
- 2) A charge will be made for the removal of the worn bushing and the installation of a new bushing for each case frame. This charge includes the new bushing and metal covering. Contact the factory for prices.
- 3) Case frames are to be shipped to Champion prepaid. They will not be accepted collect.
- 4) Reworked case frames will be returned collect to dealers and net to distributors who are on a credit basis. The return shipping charges will be added to the cost.
- 5) Each case frame must be tagged with your complete mailing address.
- 6) Repairs will not be made to the case frame other than the bushing exchange and recovering.
- 7) Each case frame will be inspected by our Material Review Board. In the event a case frame is not suitable for rebushing, we will inform you by post card. We will either send it back collect, or in thirty days, discard it depending on your reply.