

▼11CC

| | | | |
|---|---|----------|------------|
| SA00079NY | Installation of Airwolf remote mounted engine oil filter kit AFC-K008 on single and multi engine | Reissued | 12/20/2017 |
| SA00081NY | Installation of Iceman Aviation Supplies, Inc. Carburetor Ice Detector. | Reissued | 06/09/2016 |
| SA00232SE | Installation of vortex generators on the wings and tail surfaces. | Amended | 04/12/2005 |
| SA00344BO Page 1 | Installation of Parmetheus Plus LED PAR36 and PAR46 taxi and landing lights. | Amended | 08/11/2016 |
| SA00478CH | Installation of Cooper Superflite 102 Fabric. | Amended | 06/04/2015 |
| SA00823SE | Fabrication and Installation of Rainbow Flying Service front and rear wing spars and modified | Amended | 08/08/2006 |
| SA01015SE | Installation of eligible Alaska Tire and Rubber Company TSO-C62d Tires as listed in AML SA01015SE | Reissued | 03/13/2014 |
| SA01026SE (PAGE 2) | Improved fuel gascolator assembly. | Amended | 12/19/2012 |
| SA01157LA | Installation of Electronics International Model FP-5 or FP-5L fuel flow/fuel pressure instrument as | Reissued | 01/20/2005 |
| SA01158WI | Installation of Aero Enhancements UV250-1 Supplemental Instrument Panel Lightning System. | Amended | 03/29/2005 |
| SA01233SE | Manufacture and installation of Alaskan Bushwheel tail wheel and fork assembly | Reissued | 03/13/2014 |
| SA01768SE | Installation of an oil cooler system. | Amended | 05/18/2015 |
| SA01944CH(1 OF 2) | Modify airplane to fly on unleaded automotive gasoline, 87 minimum antiknock index, per ASTM | Issued | 03/05/2004 |
| SA01988SE (PAGE 1) | Installation of Electronics International Inc. Glass Panel Engine Monitor (with In-Flight Data) | Issued | 04/17/2009 |
| SA02033AT (PAGE 1) | Modification to install an air-oil separator to prevent oil from being aspirated from the engine | Amended | 07/25/2008 |
| SA02110CH (PAGE 1) | Installation of a Time Trac Data Recorder | Reissued | 01/11/2010 |
| SA02212AK (PG 1) | Replacement of existing landing and/or taxi light reflector and bulbs with high intensity discharge | Amended | 10/30/2017 |
| SA02268CH (PAGE 1) | Installation of Airwolf Filter Corp. Air Oil Separator | Reissued | 12/20/2017 |
| SA02283SE Page 1 | Installation of Electronics International Inc. Glass Panel Engine Monitor (with In Flight Data) | Amended | 06/30/2014 |
| SA02370AK | Option (1) Installation of a replacement main tank fuel valve | Reissued | 05/13/2010 |

| | | | |
|---|--|----------|------------|
| SA02402SE Page 1 | Installation of Electronics International Inc. Glass Panel Engine Monitor (with In-Flight Data) | Issued | 06/24/2014 |
| SA02428AK | Installation of a hydraulically actuated ski drag assembly | Issued | 05/02/2014 |
| SA02428SE (Page 1) | Installation of an Air Stream Switch for an electric time recording device on non-pressurized | Amended | 03/09/2017 |
| SA02520AT | Installation of M-20 Oil Separator, model 600-WP. | Issued | 05/30/2002 |
| SA02566CH | Installation of the Custom Fiberglass Molding, Inc. (CFMI) Model 1500, 2250-001, or 2250-002 | Reissued | 12/05/2015 |
| SA02987CH | Installation of the Electroair Electronic Ignition System | Amended | 07/12/2016 |
| SA04032CH | Install rocker switch assemblies | Issued | 10/08/2015 |
| SA04301CH | Attachment of fabric covering and wing leading edge | Issued | 05/21/2018 |
| SA1189GL | Installation of Ceconite 102 fabric. Limited to installation on model 11CC, serial number 11CC-121 | Amended | 07/19/2002 |
| SA1351WE (PG 1) | Replace existing fabric on wings, fuselage, empennage, and/or control surfaces, with Ceconite101 | Amended | 08/19/1983 |
| SA2078CE | Operation of airplane on unleaded automotive gasoline, 87 minimum antiknock index and leaded | Amended | 06/23/1992 |
| SA217AL | Installation of Airglas Engineering Co. Inc. Model L-1650A or L-2000A skis | Reissued | 08/18/2012 |
| SA2190NM Page 1 | Installation of electronics International Digital Volt/Amp Gauges and Accessories. | Issued | 02/16/1984 |
| SA2350NM Page 1 | Installation of Electronics International Inc digital carburetor/outside air temperature gauges | Amended | 06/06/1990 |
| SA262CE | Manufacture parts and install 12-30A electrical system. (Requires alteration of engine per STC | Issued | 01/01/1960 |
| SA2683NM | Installation of Precise Flight, Inc. stand-by vacuum system (SVS) | Amended | 03/10/2005 |
| SA2687NM (PAGE 1) | Installation of Truboplus/ Electronics Int'l gauges and switches. | Amended | 10/25/2000 |
| SA2693NM (PAGE 1) | Installation of Electronics International digital volt/amp gauges and accessories. | Amended | 12/10/2009 |
| SA2710WE | Installation of carburetor heat box bearings. | Issued | 06/15/1973 |
| SA3-115 | Model 3000 main ski and Model 1000 tail ski. | Reissued | 02/16/1993 |
| SA3-424 | Installation of Wiparie Skis Model CTF-2200 (Acft Skis) (FluiDyne) (Federal) tail ski on airplanes | Reissued | 02/16/1993 |
| SA3-670 | Install Pee-Kay Model 1500 floats with Edo struts and fittings. | Reissued | 12/23/1980 |

| | | | |
|-----------------------------------|---|-------------|------------|
| SA308EA(1 OF 2) | Installation of carburetor ice detection system 105AP in single and twin engine aircraft and single | Amended | 11/20/1978 |
| SA3358NM | Production of aircraft wing ribs as specified in W. N. Kutner's 'Report #1 STC Request for Wing | Reissued | 12/05/2008 |
| SA3829NM | Installation and Manufacturing of Aluminum Wing Spars | Amended | 04/17/2017 |
| SA4-1270 | Ceconite 101 covering of complete airplane. | Issued | 01/01/1960 |
| SA4005NM (Page 1) | Precise Flight Inc. Pulselite Control System | Amended | 12/18/2007 |
| SA4302NM (PAGE 1) | Installation of Electronics Int'l digital automatic engine analyzer. | Amended | 10/13/1989 |
| SA4305WE | Installation of GAR-AERO wheel adapters and tundra type tires on the main landing gear | Reissued | 01/14/2015 |
| SA4503NM (Page 2) | Install Ceconite covering material. | Reissued | 02/25/2011 |
| SA4624NM | Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped | Issued | 02/21/1990 |
| SA4773NM | Installation of replacement metal leading edge. | Amended | 02/05/2016 |
| SA489EA | Installation of ARP Inc. carburetor ice detection system | Amended | 12/05/2002 |
| SA5159NM(1 OF 2) | Installation of chip detector system. | Amended | 11/06/1992 |
| SA535AL | Fabrication and installation of Stoddard Aero Service wing auxiliary fuel tanks per Stoddard Aero | Reissued | 01/26/2012 |
| SA57RM | Installation of Lycoming O-235-C1, -C1A, -C1B, -C1C, -C2A, -C2B, -C2C, -H2C, -K2A, -K2B, -L2A, or | Reissued | 07/08/2009 |
| SA5924NM | Installation of RPM instrument. | Amended | 11/24/1997 |
| SA5926NM | Installation of manifold pressure instrument. | Amended | 08/15/1993 |
| SA593CH (Page 1) | Install Champion SlickSTART magneto booster system. | Reissued | 02/10/2009 |
| SA69SO | Installation of Continental C85-12F Series engine less starter and generator per C. W. Lasher | Reissued | 09/21/2012 |
| SA734GL | Superseded by STC SA01944CH. Modify airplane to fly on unleaded automotive gasoline, 87 minimum | Surrendered | 03/05/2004 |
| SA73CH | Installation of Wing Strut Fittings, P/N SAR 2-893 or SAR 2-893-1, and stiffeners, P/N 2-5009, in | Reissued | 04/22/2005 |
| SA798EA | Installation of Monitair exhaust gas combustion monitor kit. | Reissued | |