

## 15AC

<a href="#">SA00215NY</a>	Installation of CAVU Model AM100 AVMIX engine fuel/air mixture setting system.	Amended	08/14/1995
<a href="#">SA02101AK</a>	Installation and fabrication of steel wing lift strut attachment fittings.	Issued	02/20/1998
<a href="#">SA02121AK</a>	Modification of Tube No. 90 and installation of 'Dogleg' diagonal brace tubes.	Issued	07/14/1998
<a href="#">SA02197AK</a>	Installation of Hartzell HC-C2YR-1BF/F8477-4 propeller, Hartzell C-3568-P polished spinner assembly	Issued	09/24/2002
<a href="#">SA1113NW</a>	Installation of Cleveland wheels, tires (6 X 6) and brake assembly.	Amended	10/14/2008
<a href="#">SA1114NW</a>	Installation of Cleveland wheels, tires (8 or 8.5 X 6) and brake assembly.	Amended	09/09/1994
<a href="#">SA1193NW</a>	Installation of left hand pilot door.	Amended	09/09/1994
<a href="#">SA1194NW</a>	Installation of an aluminum baggage door.	Amended	09/09/1994
<a href="#">SA1285GL</a>	Surrendered and incorporated into STC SA00478CH.	Surrendered	06/14/2002
<a href="#">SA1350WE</a>	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with fiberglass cloth.	Reissued	03/06/1969
<a href="#">SA2-952</a>	Installation of fiberglass covering.	Reissued	09/10/1996
<a href="#">SA2101CE</a>	Operation of airplane on unleaded automotive gasoline, 87 minimum antiknock index and leaded	Amended	06/23/1992
<a href="#">SA21NM</a>	Installation of 50 lb baggage compartment in either or both EDO89-2000 or EDO 89A-2000 floats.	Amended	10/29/1982
<a href="#">SA3-725</a>	Prentics Aircraft lift strut fitting 61-16-1.	Issued	01/01/1960
<a href="#">SA3-731</a>	Replacement part upper and lower wing strut fittings.	Issued	01/01/1960
<a href="#">SA302NW</a>	Installation of a Lycoming O-360-A1A engine, Hartzell HC-C2YR-1BF/7666A propeller, engine mount,	Reissued	08/04/2000
<a href="#">SA306GL</a>	Installation of Lycoming O-360-A1F6D and Hartzell Model HC-C2YK-1BF/F7666A-2 propeller on aircraft	Issued	05/07/1979
<a href="#">SA308EA(1 OF 2)</a>	Installation of carburetor ice detection system 105AP in single and twin engine aircraft and single	Amended	11/20/1978
<a href="#">SA4-1210</a>	Installation of Eonnex cover on aircraft surfaces.	Reissued	08/19/1980
<a href="#">SA4-1290</a>	Ceconite 101 covering of fuselage vertical fin, horizontal stabilizer, elevator, rudder, ailerons	Issued	01/01/1960
<a href="#">SA4-1593</a>	Removal of door for parachute jumping and aerial photography operations.	Reissued	10/18/1995
<a href="#">SA4-302</a>	Installation of BN-1 propeller spinner.	Reissued	10/30/1985
<a href="#">SA4-567</a>	Glass cloth over fuselage, vertical and	Issued	01/01/1960

	horizontal stabilizers.		
<a href="#">SA4-840</a>	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	Issued	01/01/1960
<a href="#">SA424AL</a>	Installation of seat belt attachments.	Issued	04/19/1971
<a href="#">SA4624NM</a>	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
<a href="#">SA5159NM(1 OF 2)</a>	Installation of chip detector system.	Amended	11/06/1992
<a href="#">SA548CE</a>	Installation of Continental IO-346-B engine with Hartzell HC-C2YF-1A/7663 constant speed propeller.	Reissued	08/13/1997
<a href="#">SA69NW</a>	Installation of Matney's engine charge air-air filter assembly. (AA-1B, AA-1, AA-1A 1969 AND ON)	Amended	10/08/1974
<a href="#">SA798EA</a>	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972
<a href="#">SA82CH</a>	Remove existing fuel bladders and install aluminum fuel tanks.	Reissued	02/25/1997
<a href="#">SA850GL</a>	Superseded by STC SA01944CH. Modify airplane to fly on unleaded automotive gasoline, 87 minimum	Surrendered	03/05/2004
<a href="#">SA893NW</a>	Remove left, right, or both existing bladder fuel cells, install aluminum fuel tanks, and modify	Amended	04/09/1999
<a href="#">SH552NW</a>	Install cargo hook electronic scale.	Issued	01/04/1978