

50-LA

SA1301WE	Ceconite 101 covering of entire airframe.	Issued	01/01/1960
SA4624NM	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
SA489EA	Installation of ARP Inc. carburetor ice detection system	Amended	12/05/2002
SA5159NM(1 OF 2)	Installation of chip detector system.	Amended	11/06/1992
SA798EA	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972