

O-58B (Army L-3B)

SA1008WE	Installation of Poly-Fiber covering material.	Reissued	05/27/2003
SA132GL	Install metal wing ribs. (O-58B (Army L-3B), O-58B (Army L-3C S/N 058B1012 AND UP)	Reissued	09/10/2007
SA176WE	Ceconite 101 covering of wings, fuselage, ailerons, elevators and rudder.	Issued	01/01/1960
SA2-952	Installation of fiberglass covering.	Reissued	09/10/1996
SA308EA (1 OF 2)	Installation of carburetor ice detection system 105AP in single and twin engine aircraft and single	Amended	11/20/1978
SA4624NM	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
SA489EA	Installation of ARP Inc. carburetor ice detection system	Amended	12/05/2002
SA5159NM (1 OF 2)	Installation of chip detector system.	Amended	11/06/1992
SA741GL	Superseded by STC SA01944CH. Modify airplane to fly on unleaded automotive gasoline, 87 minimum	Surrendered	03/05/2004
SA798EA	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972
SA7NW	Installation of Continental C-85-8, -8F, -12, -12F engine and Sensenich M74CK propeller or	Reissued	07/08/2009