

## O-58B (Army L-3C)

<a href="#"><u>SA1008WE</u></a>	Installation of Poly-Fiber covering material.	Reissued	05/27/2003
<a href="#"><u>SA132GL</u></a>	Install metal wing ribs. (O-58B (Army L-3B), O-58B (Army L-3C S/N 058B1012 AND UP)	Reissued	09/10/2007
<a href="#"><u>SA176WE</u></a>	Ceconite 101 covering of wings, fuselage, ailerons, elevators and rudder.	Issued	01/01/1960
<a href="#"><u>SA2-952</u></a>	Installation of fiberglass covering.	Reissued	09/10/1996
<a href="#"><u>SA308EA (1 OF 2)</u></a>	Installation of carburetor ice detection system 105AP in single and twin engine aircraft and single	Amended	11/20/1978
<a href="#"><u>SA4624NM</u></a>	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
<a href="#"><u>SA489EA</u></a>	Installation of ARP Inc. carburetor ice detection system	Amended	12/05/2002
<a href="#"><u>SA5159NM (1 OF 2)</u></a>	Installation of chip detector system.	Amended	11/06/1992
<a href="#"><u>SA741GL</u></a>	Superseded by STC SA01944CH. Modify airplane to fly on unleaded automotive gasoline, 87 minimum	Surrendered	03/05/2004
<a href="#"><u>SA798EA</u></a>	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972
<a href="#"><u>SA7NW</u></a>	Installation of Continental C-85-8, -8F, -12, -12F engine and Sensenich M74CK propeller or	Reissued	07/08/2009