

S15AC

SA00215NY	Installation of CAVU Model AM100 AVMIX engine fuel/air mixture setting system.	Amended	08/14/1995
SA02101AK	Installation and fabrication of steel wing lift strut attachment fittings.	Issued	02/20/1998
SA02121AK	Modification of Tube No. 90 and installation of 'Dogleg' diagonal brace tubes.	Issued	07/14/1998
SA02197AK	Installation of Hartzell HC-C2YR-1BF/F8477-4 propeller, Hartzell C-3568-P polished spinner assembly	Issued	09/24/2002
SA1285GL	Surrendered and incorporated into STC SA00478CH.	Surrendered	06/14/2002
SA2101CE	Operation of airplane on unleaded automotive gasoline, 87 minimum antiknock index and leaded	Amended	06/23/1992
SA3-725	Prentics Aircraft lift strut fitting 61-16-1.	Issued	01/01/1960
SA3-731	Replacement part upper and lower wing strut fittings.	Issued	01/01/1960
SA302NW	Installation of a Lycoming O-360-A1A engine, Hartzell HC-C2YR-1BF/7666A propeller, engine mount,	Reissued	08/04/2000
SA308EA(1 OF 2)	Installation of carburetor ice detection system 105AP in single and twin engine aircraft and single	Amended	11/20/1978
SA4-1210	Installation of Eonnex cover on aircraft surfaces.	Reissued	08/19/1980
SA4-1290	Ceconite 101 covering of fuselage vertical fin, horizontal stabilizer, elevator, rudder, ailerons	Issued	01/01/1960
SA4-302	Installation of BN-1 propeller spinner.	Reissued	10/30/1985
SA4624NM	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
SA5159NM(1 OF 2)	Installation of chip detector system.	Amended	11/06/1992
SA548CE	Installation of Continental IO-346-B engine with Hartzell HC-C2YF-1A/7663 constant speed propeller.	Reissued	08/13/1997
SA69NW	Installation of Matney's engine charge air-air filter assembly. (AA-1B, AA-1, AA-1A 1969 AND ON)	Amended	10/08/1974
SA798EA	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972
SA893NW	Remove left, right, or both existing bladder fuel cells, install aluminum fuel tanks, and modify	Amended	04/09/1999