

SO-58B

SA01944CH(1 OF 2)	Modify airplane to fly on unleaded automotive gasoline, 87 minimum antiknock index, per ASTM	Issued	03/05/2004
SA02033AT (PAGE 1)	Modification to install an air-oil separator to prevent oil from being aspirated from the engine	Amended	07/25/2008
SA2-952	Installation of fiberglass covering.	Reissued	09/10/1996
SA308EA(1 OF 2)	Installation of carburetor ice detection system 105AP in single and twin engine aircraft and single	Amended	11/20/1978
SA4624NM	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
SA489EA	Installation of ARP Inc. carburetor ice detection system	Amended	12/05/2002
SA5159NM(1 OF 2)	Installation of chip detector system.	Amended	11/06/1992
SA741GL	Superseded by STC SA01944CH. Modify airplane to fly on unleaded automotive gasoline, 87 minimum	Surrendered	03/05/2004
SA798EA	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972