

YO-58 (Army L-3)

SA02033AT (PAGE 1)	Modification to install an air-oil separator to prevent oil from being aspirated from the engine	Amended	07/25/2008
SA1109GL	Surrendered and incorporated into STC SA00478CH.	Surrendered	06/14/2002
SA2077CE	Operation of airplane on unleaded automotive gasoline, 87 minimum antiknock index and leaded	Issued	01/24/1985
SA4-1210	Installation of Eonnex cover on aircraft surfaces.	Reissued	08/19/1980
SA4-302	Installation of BN-1 propeller spinner.	Reissued	10/30/1985
SA4624NM	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
SA5159NM (1 OF 2)	Installation of chip detector system.	Amended	11/06/1992
SA740GL	Superseded by STC SA01944CH. Modify airplane to fly on unleaded automotive gasoline, 87 minimum	Surrendered	03/05/2004
SA798EA	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972