

11AC

SA00079NY	Installation of Airwolf remote mounted engine oil filter kit AFC-K008 on single and multi engine	Reissued	12/20/2017
SA00081NY	Installation of Iceman Aviation Supplies, Inc. Carburetor Ice Detector.	Reissued	06/09/2016
SA00232SE	Installation of vortex generators on the wings and tail surfaces.	Amended	04/12/2005
SA00344BO Page 1	Installation of Parmetheus Plus LED PAR36 and PAR46 taxi and landing lights.	Amended	08/11/2016
SA00478CH	Installation of Cooper Superflite 102 Fabric.	Amended	06/04/2015
SA00823SE	Fabrication and Installation of Rainbow Flying Service front and rear wing spars and modified	Amended	08/08/2006
SA01015SE	Installation of eligible Alaska Tire and Rubber Company TSO-C62d Tires as listed in AML SA01015SE	Reissued	03/13/2014
SA01026SE (PAGE 1)	Improved fuel gascolator assembly.	Amended	12/19/2012
SA01157LA	Installation of Electronics International Model FP-5 or FP-5L fuel flow/fuel pressure instrument as	Reissued	01/20/2005
SA01158WI	Installation of Aero Enhancements UV250-1 Supplemental Instrument Panel Lightning System.	Amended	03/29/2005
SA01233SE	Manufacture and installation of Alaskan Bushwheel tail wheel and fork assembly	Reissued	03/13/2014
SA01240SE (3 OF 5)	Installation of secondary voltage indication system	Reissued	08/27/2016
SA01765SE	Installation of Alaskan Bushwheel TSO-C26d wheels, Part Number (P/N) ABI-1010	Reissued	03/13/2014
SA01988SE (PAGE 1)	Installation of Electronics International Inc. Glass Panel Engine Monitor (with In-Flight Data)	Issued	04/17/2009
SA02033AT (PAGE 1)	Modification to install an air-oil separator to prevent oil from being aspirated from the engine	Amended	07/25/2008
SA02110CH (PAGE 1)	Installation of a Time Trac Data Recorder	Reissued	01/11/2010
SA02212AK (PG 1)	Replacement of existing landing and/or taxi light reflector and bulbs with high intensity discharge	Amended	10/30/2017
SA02268CH (PAGE 1)	Installation of Airwolf Filter Corp. Air Oil Separator	Reissued	12/20/2017
SA02283SE Page 1	Installation of Electronics International Inc. Glass Panel Engine Monitor (with In Flight Data)	Amended	06/30/2014
SA02295SE	Installation of an alternate method of fastening aluminum wing ribs to wood spars	Issued	04/25/2014

SA02370AK	Option (1) Installation of a replacement main tank fuel valve	Reissued	05/13/2010
SA02402SE Page 1	Installation of Electronics International Inc. Glass Panel Engine Monitor (with In-Flight Data)	Issued	06/24/2014
SA02428AK	Installation of a hydraulically actuated ski drag assembly	Issued	05/02/2014
SA02503AK (Page 2)	Installation of AMSAFE State of the Art Restraint System (SOARS) inflatable restraints	Issued	07/12/2018
SA02520AT	Installation of M-20 Oil Separator, model 600-WP.	Issued	05/30/2002
SA02566CH	Installation of the Custom Fiberglass Molding, Inc. (CFMI) Model 1500, 2250-001, or 2250-002	Reissued	12/05/2015
SA02987CH	Installation of the Electroair Electronic Ignition System	Amended	07/12/2016
SA03898NY	Installation and maintenance of ORATEX covering and coating material	Issued	03/20/2017
SA04032CH	Install rocker switch assemblies	Issued	10/08/2015
SA04202AT	Replacement of either a 65 horsepower Continental A65-8 or A65-8F engine with a 85 horsepower	Amended	12/07/2017
SA04301CH	Attachment of fabric covering and wing leading edge	Issued	05/21/2018
SA10077SC	Installation of push-button starter system.	Reissued	12/13/2016
SA1008WE	Installation of Poly-Fiber covering material.	Reissued	05/27/2003
SA1057GL	Surrendered and incorporated into STC SA00478CH.	Surrendered	06/14/2002
SA1350WE	Replace existing fabric on wings, fuselage, empennage and/or control surfaces with fiberglass cloth.	Reissued	03/06/1969
SA1351WE (PG 1)	Replace existing fabric on wings, fuselage, empennage, and/or control surfaces, with Ceconite101	Amended	08/19/1983
SA150SO	Installation of surface fabric attachment clip.	Reissued	06/03/1991
SA1626NM Page 1	Installation of Electronics Int'l Digital EGT/CHT Instruments and accessories. (201 Series)	Amended	03/09/1993
SA19SO	Installation of left and/or right auxiliary fuel tank(s).	Reissued	06/24/1996
SA2079CE	Operation of airplane on unleaded automotive gasoline, 87 minimum antiknock index and leaded	Amended	06/23/1992
SA217AL	Installation of Airglas Engineering Co. Inc. Model L-1650A or L-2000A skis	Reissued	08/18/2012
SA2190NM Page 1	Installation of electronics International Digital Volt/Amp Gauges and Accessories.	Issued	02/16/1984
SA2350NM Page 1	Installation of Electronics International Inc digital	Amended	06/06/1990

	carburetor/outside air temperature gauges		
SA241CH	Install Ceconite 101 fabric.	Amended	07/11/2006
SA2683NM	Installation of Precise Flight, Inc. stand-by vacuum system (SVS)	Amended	03/10/2005
SA2687NM (PAGE 1)	Installation of Truboplus/ Electronics Int'l gauges and switches.	Amended	10/25/2000
SA2693NM (PAGE 1)	Installation of Electronics International digital volt/amp gauges and accessories.	Amended	12/10/2009
SA2710WE	Installation of carburetor heat box bearings.	Issued	06/15/1973
SA2857SO	Installation of Basic Type BPE-14, Model No. 1008 Air Driven alternator.	Issued	11/07/1990
SA3-215	Laminated plastic and fiberglass nose cowl D-576P.	Issued	01/01/1960
SA3-435	Install Continental A-75-8 or A-75-8F engine.	Reissued	01/29/1999
SA308EA (1 OF 2)	Installation of carburetor ice detection system 105AP in single and twin engine aircraft and single	Amended	11/20/1978
SA3358NM	Production of aircraft wing ribs as specified in W. N. Kutner's 'Report #1 STC Request for Wing	Reissued	12/05/2008
SA345CE	Remove right door.	Issued	08/03/1965
SA3829NM	Installation and Manufacturing of Aluminum Wing Spars	Amended	04/17/2017
SA3862NM Page 1	Installation of Electronics International Primary TIT/EGT/CHT instruments, remote switches and	Amended	04/25/1988
SA4-1210	Installation of Eonnex cover on aircraft surfaces.	Reissued	08/19/1980
SA4-1276	Ceconite 101 covering of complete airplane.	Issued	01/01/1960
SA4-302	Installation of BN-1 propeller spinner.	Reissued	10/30/1985
SA4-369	Lift strut assemblies.	Issued	01/01/1960
SA4-444	Carburetor and cabin hot air muff with replaceable air inlet and outlet.	Issued	01/01/1960
SA4-789	McCauley 1B90-CM/7045 propeller on Continental A-65-8 engine.	Issued	01/01/1960
SA4-840	Fabric replaced with glass cloth on wings, fuselage, empennage and/or control surfaces.	Issued	01/01/1960
SA4-99	Fiberglass cloth with resin over muslin applied.	Issued	01/01/1960
SA4005NM (Page 1)	Precise Flight Inc. Pulselite Control System	Amended	12/18/2007
SA4302NM (PAGE 1)	Installation of Electronics Int'l digital automatic engine analyzer.	Amended	10/13/1989
SA4305WE	Installation of GAR-AERO wheel adapters and tundra type tires on the main landing gear	Reissued	01/14/2015
SA4503NM (Page 2)	Install Ceconite covering material.	Reissued	02/25/2011

SA4773NM	Installation of replacement metal leading edge.	Amended	02/05/2016
SA489EA	Installation of ARP Inc. carburetor ice detection system	Amended	12/05/2002
SA535AL	Fabrication and installation of Stoddard Aero Service wing auxiliary fuel tanks per Stoddard Aero	Reissued	01/26/2012
SA5755NM	Installation of a propeller anti theft device.	Issued	08/05/1992
SA57RM	Installation of Lycoming O-235-C1, -C1A, -C1B, -C1C, -C2A, -C2B, -C2C, -H2C, -K2A, -K2B, -L2A, or	Reissued	07/08/2009
SA5924NM	Installation of RPM instrument.	Amended	11/24/1997
SA5925NM	Installation of oil pressure/temperature instrument.	Amended	12/08/1997
SA5926NM	Installation of manifold pressure instrument.	Amended	08/15/1993
SA593CH (Page 1)	Install Champion SlickSTART magneto booster system.	Reissued	02/10/2009
SA685NW	Installation of a Lycoming engine, a Sensenich propeller, PA18 landing gear, and drooped wing tips	Issued	11/15/1978
SA733GL	Superseded by STC SA01944CH. Modify airplane to fly on unleaded automotive gasoline, 87 minimum	Surrendered	03/05/2004
SA73CH	Installation of Wing Strut Fittings, P/N SAR 2-893 or SAR 2-893-1, and stiffeners, P/N 2-5009, in	Reissued	04/22/2005
SA7965SW	Application of fabric and polyurethane finishing system.	Reissued	03/01/2018
SA798EA	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972
SA8075SW (PAGE 1)	Installation of fiberglass covering. (M-62 SERIES PT-19) (G-73 SCHWEIZER)	Reissued	11/10/2003
SA89AL	Installation of auxiliary fuel tanks.	Amended	02/07/1975