

50-C

SA4-288	BN-1 propeller spinner.	Issued	01/01/1960
SA4624NM	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
SA742GL	Superseded by STC SA01944CH. Modify airplane to fly on unleaded automotive gasoline, 87 minimum	Surrendered	03/05/2004