

**65-LA**

<a href="#">SA1301WE</a>	Ceconite 101 covering of entire airframe.	Issued	01/01/1960
<a href="#">SA4624NM</a>	Installation of F. Atlee Dodge springs 2097 and 2127 to replace bungee cords on ski equipped	Issued	02/21/1990
<a href="#">SA489EA</a>	Installation of ARP Inc. carburetor ice detection system	Amended	12/05/2002
<a href="#">SA5159NM(1 OF 2)</a>	Installation of chip detector system.	Amended	11/06/1992
<a href="#">SA798EA</a>	Installation of Monitair exhaust gas combustion monitor kit.	Reissued	02/14/1972